

575M Updates (US Models)

Assembly Number	Part No/ Table No	Description	Comments
43847	187744/6	Cam Timing Belt	Belt change interval went from 3 to 5 years
48712	190996/55	Rear Shock Absorber	New rear shocks only
49049	197426/137	F1 Trans ECU/TCU	New F1 Transmission Control Unit/ECU
49203	198455/15 198456/15	F1 Motronic ECUx2 Manual Motronic ECUx2	Ignition/injection ECU upgrade
49879	67129000/100 67506000/100 194414/139	R.H. Rear Fender CD Changer Bracket Becker 6 CD Unit	R.H. rear fender (only) and bracket and CD changer bracket updated for change from Sony to Becker 6 CD player
50297	163865/41	Brake Pedal Drilled Pad/Plate	Moved one set of holes to the left, 55 mm vs 35 mm from gas pedal, easily reversible
51797	200995/21 200996/21 200997/21 200998/21	R.H. Center Pipe L.H. Center Pipe R.H. Muffler L.H Muffler	Eliminated central muffler/resonator, replaced with straight center pipes, new rear mufflers
52509	67979100/62 67979000/62	A/C Evaporator Unit A/C ECU	Major A/C change, new evaporator, addition of A/C ECU
52556	202757/15 202756/15 202140/51 190405/51 205433/129 207542/129 202954/134	F1 Motronic ECUx2 Manual Motronic ECUx2 Steering Column Support Steering Angle Sensor F Control Station Harness R Control Station Harness Shock Absorber ECU	Major steering sensor addition package, new shock ECU, Motronic ECU, control station wiring harnesses F (airbag/dash) & R (F1), steering column covers/supports (small parts omitted here). Earlier cars cannot be upgraded ¹ . HGTC components compatible with new harnesses.
55769	211423/15 211422/15 217735/53 205290/55 210577/134	F1 Motronic ECUx2 Manual Motronic ECUx2 Front Shock Absorber Rear Shock Absorber Shock Absorber ECU	Major upgrade with new shocks, supports, cups, Hyperblocks, shock ECU, Motronic ECU (small parts omitted here). Cars after Assembly 52556 can be upgraded. HGTC components compatible.
57934 Eng 90577	206075/29 214369/133	F1 Clutch Sensor kit F1 Cable	New F1 clutch sensor kit with waterproof connectors and new matching F1 cable
Eng 72331	196495/27 196496/27 184038/27	RH Engine Cables LH Engine Cables Complete Water Pump	Changed from unique WP to one common to 456/456M. WP temp sensor deleted. WP parts available separately. New harness.
Trans 369	194327/42	F1 Hydraulic Control	Complete new F1 system
Trans 1891	212821/42	F1 Hydraulic Control	Complete new F1 system

Notes

1. HGTC Shock Absorber ECU 210578 will fit cars earlier than 52556, but will give a Suspension Warning Lamp due to the missing Steering Position Sensor input. This HGTC ECU will fit and operate properly on all cars 52556 or later. Believe the HGTC F1 ECU 211426 will fit and operate properly on all F1 575Ms, but not 100% sure.