

Exterior: Suggested Maximum Deductions (05/2018)



Evaluate each item for Authenticity and Condition

<u>CATEGORY</u>	<u>Max Ded</u>	<u>MINOR</u>	<u>SIGNIFICANT</u>	<u>MAJOR</u>	<u>MAX DEDUCTION</u>
COACHWORK Body, Fenders,	5	Small chips evidence of driving -0 Small metal finish flaws -1/2 Unobtrusive protective film -0 License plate frames -0	Obtrusive chips -1 Significant dents -1 Each NOR bumper -1 Messy/discolored film -1 Obtrusive mirrors, frames, etc. -1	Misshapen or modified body -3 Out of 10 year period rebody -3 Each missing bumper -2 Visible major rust -2 Some colored vinyl wrap -2	Out of 10 year period rebody -5 (Pebble Beach) Major use of colored vinyl wrap -5
DOORS, HOOD TRUNK Fit/Operation	3	Fit & finish not similar to original characteristics of the different coachwork houses -1/2	Each door noticeably sagging -1 Each one NOR fit or operation -1	Several issues -2	All departing from the original fit and finish of the body maker -3
TOP	3	Stain or wear -1/2	NOR style material -1 NOR shape, fit or frame -1	NOR shape and fit -2	NOR shape, fit & frame -3 Missing or INOP top -3
PAINT	3	Minor scratches -1/2 Any period non-Ferrari color is acceptable -0	Noticeable flaws -1	Major flaws -2	Serious deterioration and flaws -3
PLATING Bumpers, etc	2	Scratches or blemishes -1/2	Each one NOR quality -1	Two NOR -2	Three NOR -2
LIGHTS Type & Fitting	4	NOR style screws -1/2 Minor marker light NOR -1/2 Replacement bulbs -0	Each NOR Lens or Housing -1 Each Light NOR fit or style -1	X	Maximum -4
TRIM & Emblems	2	Scratches or blemishes -1/2 Slightly NOR appearance -1/2	NOR Emblem -1 Missing Emblem -1	X	Maximum -2
GLASS PLEXIGLAS	2	Small chips evidence of driving -0 Obtrusive chips or scratches -1/2 Replacement glass matching original characteristics -0	Obtrusive breakage -1 Several obtrusive chips/scratches including convertible windows -1	X	No Glass or Plexiglas -2 NOR size -2
RUBBER Window Felt	2	Tears or rips -1/2 Slightly NOR appearance -1/2	Rubber or felt missing -1 Rubber or felt totally NOR type -1	X	Maximum -2
WHEELS & TIRES	3	NOR DECAL -1/2 Original spare -0	NOR paint or plating -1 Damaged spoke -1 NOR tire dimensions & profile -1	Four NOR knock-offs -2 Four NOR wheels -2 Four NOR profiles -2	Maximum -3

X=Does Not Apply